

AAMJIWNAANG FIRST NATION

Notification Report

March 2020

Wilson Plain Jr. – Emergency Management Planner

June 4, 2020

Report of notifications received from local industries, CVECO, Ministry of the Environment, Conservation and Parks (MECP) including Spills Action Centre (SAC) and MyCNN notifications.

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

Incidents/Notifications reported for the month of March 2020.

- 40 notifications were received
- No phone calls, no text messages, 2 emails and 20 CVECO notifications were received
- 2 CVECO 'Codes' were issued. 18 CVECO 'Information Notices' were issued.
- 12 Aamjiwnaang Notifications were sent out (ANS or FB)

Ministry of the Environment, Conservation and Parks (MECP) Information/Update emails received: 18

Community Inquiries: No inquiries were received from community members regarding incidents near Aamjiwnaang.

*** Beginning March 13, 2020, the City of Sarnia Primary Control group began daily teleconferences to discuss the COVID – 19 Pandemic along with local issues that may have arisen. During this time, Chief Plain, Patrick Nahmabin and Wilson Plain Jr. participated in the daily calls. They, and the related emails are not included in this information log sheet due to the overwhelming number that were received.

*** The Lambton County Emergency Control Group also began daily teleconferences on March 16, 2020 with County Councilors, Chief Administrative Officer and local Community Emergency Management Coordinators. Wilson Plain Jr. attends, representing Aamjiwnaang First Nation.

Date	Time of Issue	Time of All Clear	Company	Type of Notice	Notification Received	Follow -Up (if req'd)	ANS or FB
Mar 2	8:06 am		INEOS Styrolution	Information Notice	Ineos Styrolution at 872 tashmoo avenue issued an information for smokey loading rack incinerator and has been cleared		
Mar 3	9:05 pm	11:15 pm	Shell Canada	Information Notice	INFORMATION ONLY for Shell Canada XJF737 for odour at north dock sump		
Mar 3	9:07 am		Shell Canada	MECP (SAC) Information Email>>>	MECP Reference Number: 7207-BMD46T Date/Time Incident Occurred: 2020/03/03 – 20:30 Date/Time Incident Reported to MECP: 2020/03/03 – 20:50 Company name (if known): Shell Location of Incident: 150 St. Clair Parkway, St. Clair Company description of incident and actual/expected duration: diesel fumes from sump Company description of actual/expected adverse effect: fumes Actions being taken by the facility to respond: vac truck to pump out sump Agencies/Parties responding: Tams		
Mar 4	6:56 pm		Suncor	MECP (SAC) Information Email>>>	MECP Reference Number: 2501-BMDVRH Date/Time Incident Occurred: 18:40 03/04/2020 Date/Time Incident Reported to MECP: 18:40 03/04/2020 Company name (if known): Suncor Energy Location of Incident: 1900 River Rd, Sarnia Company description of incident and actual/expected duration: They are doing planned maintenance on a tank. Duration of maintenance is unknown. Company description of actual/expected adverse effect: They don't expect any odours during the maintenance, but as a precaution they are doing air monitoring. Actions being taken by the facility to respond: They are monitoring the air quality Agencies/Parties responding: N/A		
Mar 4	7:08 pm		Suncor	Information Notice	INFORMATION ISSUED FOR SUNCOR SARNIA REFINERY FOR PLANNED MAINTENANCE ON SITE TANK. POTENTIAL IMPACT ON AIR QUALITY.		

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

Mar 4	7:32 pm		Suncor	Information Notice	information issued for Suncor Sarnia refinery. Planned maintenance on site tank. Odors not expected, will be monitoring to assess any potential impact to air quality.		
Mar 6	9:19 am	3:53 pm	INEOS Styrolution	Information Notice	INFORMATION ONLY equipment start up possible high flaring		
Mar 8	11:44 am	12:27 pm	NOVA Corunna	CVECO Code 8	Code 8 was issued for vcw454 NOVA corunna for a fire in heater number 4		
Mar 9	3:54 PM		Imperial	MECP (SAC) Information Email>>>	<p>MECP Reference Number: 0024-BMJPYL</p> <p>Date/Time Incident Occurred: March 09, 2020 at 14:11 PM</p> <p>Date/Time Incident Reported to MECP: Mar 09, 2020 14:44 PM</p> <p>Company name (if known): Imperial Oil Sarnia Refinery</p> <p>Location of Incident: 602 Christina St South, Sarnia</p> <p>Company description of incident and actual/expected duration: process upset with safety valve release for 5 seconds</p> <p>Company description of actual/expected adverse effect: No adverse impacts</p> <p>Actions being taken by the facility to respond: N/A</p> <p>Agencies/Parties responding: MECP Sarnia</p>		FB
Mar 10	3:06 am	4:53 am Mar 11	Plains Midstream	Information Notice	PLAINS MIDSTREAM XNZ861 ISSUING INFORMATION FOR POTENTIAL FLARING AND NOISE FROM PLANT START UP.		
Mar 10	12:06 pm		Shell Canada	MECP Update Information Email>>>	<p>Update Information E-mail for Aamjiwnaang First Nation –</p> <p>Odour Complaint</p> <p>MECP Reference Number: 1121-BLD5DS</p> <p>Date/Time Incident Occurred: Jan 31, 2020 9:45 pm</p> <p>Date/Time Incident Reported to MECP: Jan 31, 2020 9:52 pm</p> <p>Company name (if known): Shell Canada Products</p> <p>Location of Incident: Along residential area, Vidal Street, Sarnia</p> <p>What Happened?</p> <p>This update is for an odour complaint on January 31, 2020 with an initial notification to Aamjiwnaang First Nation on January 31, 2020. A resident called the ministry's Spills Action Centre to report a strong chemical odour and believed the odour was from the Shell refinery. According to the Clean Air Sarnia and Area air monitoring network, the wind conditions were calm and from the south and southwest at the time of the call. All air monitoring stations were reporting in the "good" range. Ministry staff were unable to detect an odour during an area inspection.</p> <p>What Actions Were Taken?</p> <p>The Spills Action Centre called Shell Canada Products at approximately 11:04 pm to notify of the odour complaint. Shell staff reported no upsets or activities that could be the source of the odour. Shell staff checked for odours and used air monitors at approximately 11:32 pm. There were no odours or pollutants detected on the equipment. Ministry staff inspected the area at approximately 11:39 pm. Ministry staff observed light winds from the southwest and detected a slight odour during the inspection but could not track it with the low wind conditions. Ministry staff conducted air quality monitoring using handheld equipment to measure volatile organic compounds and sulphur dioxide. There was no detection of pollutants with the equipment. Ministry staff contacted Shell and inspected the area with Shell staff around their facility for odours. No odours were detected. Ministry staff followed up with the resident on February 3, 2020 to report ministry response and results.</p> <p>Other Agencies/Parties responding: No other agencies</p>		FB
Mar 10	12:10 pm		Shell Canada	MECP Update	<p>Update Information E-mail for Aamjiwnaang First Nation –</p> <p>Odour Complaint from Aamjiwnaang Day Care</p> <p>MECP Reference Number: 5831-BKLJLR</p>		FB

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

				Information Email>>>	<p>Date/Time Incident Occurred: Jan 7, 2020 at 8:20 am Date/Time Incident Reported to MECP: Jan 7, 2020 at 9:09 am Company name (if known): Shell Canada Location of Incident: 1900 Virgil Ave. What Happened? This update is for an odour complaint on January 7, 2020 with an initial notification to Aamjiwnaang First Nation on January 7, 2020. An employee of the Aamjiwnaang day care called the Spills Action Centre to report a strong odour resembling boiled cabbage. According to the Clean Air Sarnia and Area website, the winds were from the south and very light. The air monitoring stations were reading in the “good” range at the time of the complaint. Ministry staff confirmed the odour and determined the source was likely Shell Canada. What Actions Were Taken? Ministry staff inspected the area at approximately 9:30 am on January 7, 2020 and conducted air monitoring for volatile organic compounds, sulphur dioxide and hydrogen sulphide at three locations in the area of the complaints. There was no detection of compounds with the monitors. Ministry staff contacted Shell, who is located upwind of the area of the complaints to gather information on their operations and activities. The company confirmed they were working on a piece of equipment, which aligns with the timing of the odour complaint. The company provided the ministry with details of their activities on January 22 and on February 19, 2020. The company’s investigation into the possible cause of the odour was not conclusive. The company’s activity was considered normal with no upsets or issues with the process. The company stopped the activity at the time of the complaint and started again on January 27, 2020. The company modified their process to reduce the potential for odours. The company also checked for odours during the process and no odours were detected. The work was completed on January 30, 2020. Agencies/Parties responding: No other agencies.</p>		
Mar 10	12:15 pm	Shell Canada		MECP Update Information Email>>>	<p>Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint – Chippewa Cres MECP Reference Number: 1123-BKLJ92 Date/Time Incident Occurred: Jan 7, 2020 at 8:40 am Date/Time Incident Reported to MECP: Jan 7, 2020 at 8:51 am Company name (if known): Shell Canada Location of Incident: Chippewa Crescent What Happened? This update is for an odour complaint on January 7, 2020 with an initial notification to Aamjiwnaang First Nation on January 7, 2020. A resident called the ministry’s Spills Action Centre to report a strong chemical odour. According to the Clean Air Sarnia and Area website, the winds were from the south and very light. The air monitoring stations were reading in the “good” range at the time of the complaint. Ministry staff confirmed the odour and determined the source was likely Shell Canada. What Actions Were Taken? Ministry staff inspected the area at approximately 9:30 am on January 7, 2020 and conducted air monitoring for volatile organic compounds, sulphur dioxide and hydrogen sulphide at three locations in the area of the complaints. There was no detection of compounds during monitoring. Ministry staff contacted Shell, who is located upwind of the area of the complaints to gather information on their operations and activities. The company confirmed they were working on a piece of equipment, which aligns with the timing of the odour</p>		FB

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

					<p>complaint. The company provided the ministry with details of their activities on January 22 and on February 19, 2020. The company's investigation into the possible cause of the odour was not conclusive. The company's activity was considered normal with no upsets or issues with the process. The company stopped the activity at the time of the complaint and started again on January 27, 2020. The company modified their process to reduce the potential for odours. The company also checked for odours during the process and no odours were detected. The work was completed on January 30, 2020.</p> <p>Agencies/Parties responding: No other agencies</p>		
Mar 10	12:18 pm			<p style="text-align: center;">MECP Update Information Email>>></p>	<p>Update Information E-mail for Aamjiwnaang First Nation – Noise and Rumbling Complaint MECP Reference Number: 8834-BLW6GX Date/Time Incident Occurred: Feb 17, 2020 10:15 pm Date/Time Incident Reported to MECP: Feb 17, 2020 10:48 pm Company name (if known): Possibly Arlanxeo Location of Incident: 1265 Vidal Street South, Sarnia What Happened? This update is for a noise and rumbling complaint on February 17, 2020 with an initial notification to Aamjiwnaang First Nation on February 17, 2020. A resident called the ministry's Spills Action Centre to report rumbling noise to the east. According to the Clean Air and Sarnia Area air monitoring network, the winds were light and from the east. A possible source of noise was Arlanxeo who recently started flaring due to a unit upset. What Actions Were Taken? The Spills Action Centre contacted the City of Sarnia and Sarnia Police Services to ask if there were any issues reported that would cause the rumbling. Sarnia Police noted that Arlanxeo reported high flaring and noise due to a unit upset. The Spills Action Centre contacted Arlanxeo who confirmed the high flaring and noise. Local ministry staff contacted Arlanxeo to gather additional details. Ministry staff inspected the area at approximately 1:30 am on February 18, 2020. At the time of the inspection, the flare appeared to be normal and no odours were detected downwind of the company. Ministry staff monitored for volatile organic compounds and sulphur dioxide. There was no detection of compounds. Arlanxeo provided more details on the cause of the flare and the materials sent to the flare, which was propane and ethylene. Other Agencies/Parties responding: No other agencies.</p>		FB
Mar 10	12:20 pm		Unknown	<p style="text-align: center;">MECP Update Information Email>>></p>	<p>Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint in the Vicinity of St. Clair Parkway and Marlborough Lane MECP Reference Number: 0144-BLY4DB Date/Time Incident Occurred: Feb 19, 2020 8:45 pm Date/Time Incident Reported to MECP: Feb 19, 2020 9:00 pm Company name (if known): Unknown Location of Incident: St. Clair Parkway and Marlborough Lane What Happened? This update is for an odour complaint on February 19, 2020 with an initial notification to Aamjiwnaang First Nation on February 19, 2020. A resident called the ministry's Spills Action Centre to report a sulphur and chlorine odour. According to the Clean Air and Sarnia Area air monitoring website, the winds were from the west and very low at the time of the complaint. All stations were reading in the "good" range. The ministry could not confirm an odour during an inspection. What Actions Were Taken? Ministry staff inspected the area for odours at approximately 10:23 pm. There were no unusual odours found during the inspection. Ministry staff observed the</p>		FB

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

					winds were from the west at the time of the inspection and were higher than at the time of the complaint. Ministry staff monitored the area for sulphur dioxide using hand-held equipment. There was no detection of sulphur dioxide. Other Agencies/Parties responding: No other agencies.		
Mar 13	7:17 am	5:04 pm	CF Industries	Information Notice	CF INDUSTRIES LOCATED AT 161 BICKFORD LINE IN COURTRIGHT IS ISSUING AN INFORMATION ONLY FOR POSSIBLE HIGH FLARING, AS THEY ARE PURGING A SECTION OUTAGE IN A2 AT THEIR NITROGEN COMPLEX. WIND IS NOW OUT OF THE WEST AT 25 KILOMETRES PER HOUR.		
Mar 13	8:02 pm		Suncor	MECP (SAC) Information Email>>>	MECP Reference Number: 7530-BMNVP5 Date/Time Incident Occurred: 2020/03/13 at 1936h Date/Time Incident Reported to MECP: 2020/03/13 at 1936h Company name (if known): Suncor Location of Incident: 1900 River Road, Sarnia Company description of incident and actual/expected duration: Unit upset at facility. Company description of actual/expected adverse effect: potential flaring and increased noise from facility. Actions being taken by the facility to respond: preparing for potential flaring as required. Agencies/Parties responding: Suncor		
Mar 13	8:16 pm	2:45 am Mar 16	Suncor	Information Notice	INFORMATION ONLY. PLEASE BE ADVISED SUNCOR SARNIA REFINERY IS IN THE PROCESS OF SAFELY SHUTTING DOWN A PROCESS UNIT. AS A RESULT, THERE MAY BE THE POTENTIAL FOR FLARING, NOISE AND ODOR.		
Mar 13	9:01 pm		Air Products	Information Notice	INFORMATION ONLY. AIR PRODUCTS IS FLARING AND VENTING STEAM AS PART OF PLANT TRIP		
Mar 13	9:23 pm		Air Products	MECP (SAC) Information Email>>>	MECP Reference Number: 4332-BMP39P Date/Time Incident Occurred: 13March2020 @ 16:30 Date/Time Incident Reported to MECP: 13March2020 @ 21:03 Company name (if known): Air Products Location of Incident: 150 St. Clair Parkway, Corunna Company description of incident and actual/expected duration: Flaring higher than normal due to plant trip. Anticipated to be back to normal flaring around 02:00 on 14March2020 Company description of actual/expected adverse effect: Higher visible flare. Actions being taken by the facility to respond: Troubleshooting to correct the problem to bring flare back to normal levels. CVECO information code issued. Agencies/Parties responding: MECP SAC (Spills Action Centre) has received the information call from Air Products.		FB
Mar 14	2:31 am	7:18 am Mar 15	Plains Midstream	Information Notice	Information only issued for Plains Midstream at 1182 Plank Rd, XNZ861 for potential flaring and noise from plant start up.		
Mar 14	8:10 pm	4:30 pm Mar 15	Arlanxeo	Information Notice	INFORMATION ONLY. LOUD NOISE AND POSSIBLE HIGH FLARING DUE TO COMPRESSOR START UP AT BUTYL UNIT (500 KENNY STREET)		
Mar 16	9:55 am		Shell Canada	MECP Update Information Email>>>	Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint MECP Reference Number: 1121-BLD5DS Date/Time Incident Occurred: Jan 31/2020 at 9:45 pm Date/Time Incident Reported to MECP: Jan 31/2020 at 9:52 pm Company name (if known): Shell Canada Products Location of Incident: Along residential area, Vidal Street, Sarnia What Happened?		FB

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

				<p>This update is for an odour complaint on January 31, 2020 with an initial notification to Aamjiwnaang First Nation on January 31, 2020. A resident called the ministry's Spills Action Centre to report a strong chemical odour and believed the odour was from the Shell refinery. According to the Clean Air Sarnia and Area air monitoring network, the wind conditions were calm and from the south and southwest at the time of the call. All air monitoring stations were reporting in the "good" range. Ministry staff were unable to detect an odour during an area inspection.</p> <p>What Actions Were Taken? The Spills Action Centre called Shell Canada Products at approximately 11:04 pm to notify of the odour complaint. Shell staff reported no upsets or activities that could be the source of the odour. Shell staff checked for odours and used air monitors at approximately 11:32 pm. There were no odours or pollutants detected on the equipment. Ministry staff inspected the area at approximately 11:39 pm. Ministry staff observed light winds from the southwest and detected a slight odour during the inspection but could not track it with the low wind conditions. Ministry staff conducted air quality monitoring using handheld equipment to measure volatile organic compounds and sulphur dioxide. There was no detection of pollutants with the equipment. Ministry staff contacted Shell and inspected the area with Shell staff around their facility for odours. No odours were detected. Ministry staff followed up with the resident on February 3, 2020 to report ministry response and results.</p> <p>Other Agencies/Parties responding: No other agencies</p>		
FBM ar 16	9:57 am	Shell Canada	MECP Update Information Email>>>	<p>Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint from Aamjiwnaang Day Care MECP Reference Number: 5831-BKLJLR Date/Time Incident Occurred: January 7, 2020 at 8:20 am Date/Time Incident Reported to MECP: January 7, 2020 at 9:09 am Company name (if known): Shell Canada Location of Incident: 1900 Virgil Ave. What Happened? This update is for an odour complaint on January 7, 2020 with an initial notification to Aamjiwnaang First Nation on January 7, 2020. An employee of the Aamjiwnaang day care called the Spills Action Centre to report a strong odour resembling boiled cabbage. According to the Clean Air Sarnia and Area website, the winds were from the south and very light. The air monitoring stations were reading in the "good" range at the time of the complaint. Ministry staff confirmed the odour and determined the source was likely Shell Canada.</p> <p>What Actions Were Taken? Ministry staff inspected the area at approximately 9:30 am on January 7, 2020 and conducted air monitoring for volatile organic compounds, sulphur dioxide and hydrogen sulphide at three locations in the area of the complaints. There was no detection of compounds with the monitors. Ministry staff contacted Shell, who is located upwind of the area of the complaints to gather information on their operations and activities. The company confirmed they were working on a piece of equipment, which aligns with the timing of the odour complaint. The company provided the ministry with details of their activities on January 22 and on February 19, 2020. The company's investigation into the possible cause of the odour was not conclusive. The company's activity was considered normal with no upsets or issues with the process. The company stopped the activity at the time of the complaint and started</p>		FB

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

					<p>again on January 27, 2020. The company modified their process to reduce the potential for odours. The company also checked for odours during the process and no odours were detected. The work was completed on January 30, 2020.</p> <p>Agencies/Parties responding: No other agencies.</p>		
Mar 16	9:59 am	Shell Canada	MECP Update Information Email>>>	<p>Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint – Chippewa Cres MECP Reference Number: 1123-BKLJ92 Date/Time Incident Occurred: January 7, 2020 at 8:40 am Date/Time Incident Reported to MECP: January 7, 2020 at 8:51 am Company name (if known): Shell Canada Location of Incident: Chippewa Crescent What Happened? This update is for an odour complaint on January 7, 2020 with an initial notification to Aamjiwnaang First Nation on January 7, 2020. A resident called the ministry’s Spills Action Centre to report a strong chemical odour. According to the Clean Air Sarnia and Area website, the winds were from the south and very light. The air monitoring stations were reading in the “good” range at the time of the complaint. Ministry staff confirmed the odour and determined the source was likely Shell Canada. What Actions Were Taken? Ministry staff inspected the area at approximately 9:30 am on January 7, 2020 and conducted air monitoring for volatile organic compounds, sulphur dioxide and hydrogen sulphide at three locations in the area of the complaints. There was no detection of compounds during monitoring. Ministry staff contacted Shell, who is located upwind of the area of the complaints to gather information on their operations and activities. The company confirmed they were working on a piece of equipment, which aligns with the timing of the odour complaint. The company provided the ministry with details of their activities on January 22 and on February 19, 2020. The company’s investigation into the possible cause of the odour was not conclusive. The company’s activity was considered normal with no upsets or issues with the process. The company stopped the activity at the time of the complaint and started again on January 27, 2020. The company modified their process to reduce the potential for odours. The company also checked for odours during the process and no odours were detected. The work was completed on January 30, 2020.</p> <p>Agencies/Parties responding: No other agencies</p>		FB	
Mar 16	10:01 am	Arlanxeo	MECP Update Information Email>>>	<p>Update Information E-mail for Aamjiwnaang First Nation – Noise and Rumbling Complaint MECP Reference Number: 8834-BLW6GX Date/Time Incident Occurred: February 17, 2020 at 10:15 pm Date/Time Incident Reported to MECP: February 17, 2020 at 10:48 pm Company name (if known): Possibly Arlanxeo Location of Incident: 1265 Vidal Street South, Sarnia What Happened? This update is for a noise and rumbling complaint on February 17, 2020 with an initial notification to Aamjiwnaang First Nation on February 17, 2020. A resident called the ministry’s Spills Action Centre to report rumbling noise to the east. According to the Clean Air and Sarnia Area air monitoring network, the winds were light and from the east. A possible source of noise was Arlanxeo who recently started flaring due to a unit upset. What Actions Were Taken?</p>		FB	

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

					<p>The Spills Action Centre contacted the City of Sarnia and Sarnia Police Services to ask if there were any issues reported that would cause the rumbling. Sarnia Police noted that Arlanxeo reported high flaring and noise due to a unit upset. The Spills Action Centre contacted Arlanxeo who confirmed the high flaring and noise. Local ministry staff contacted Arlanxeo to gather additional details. Ministry staff inspected the area at approximately 1:30 am on February 18, 2020. At the time of the inspection, the flare appeared to be normal and no odours were detected downwind of the company. Ministry staff monitored for volatile organic compounds and sulphur dioxide. There was no detection of compounds. Arlanxeo provided more details on the cause of the flare and the materials sent to the flare, which was propane and ethylene.</p> <p>Other Agencies/Parties responding: No other agencies.</p>		
Mar 16	10:02 am		Unknown	<p>MECP Update Information Email>>></p>	<p>Update Information E-mail for Aamjiwnaang First Nation – Odour Complaint in the Vicinity of St. Clair Parkway and Marlborough Lane MECP Reference Number: 0144-BLY4DB Date/Time Incident Occurred: February 19, 2020 at 8:45 pm Date/Time Incident Reported to MECP: February 19, 2020 at 9:00 pm Company name (if known): Unknown Location of Incident: St. Clair Parkway and Marlborough Lane What Happened? This update is for an odour complaint on February 19, 2020 with an initial notification to Aamjiwnaang First Nation on February 19, 2020. A resident called the ministry’s Spills Action Centre to report a sulphur and chlorine odour. According to the Clean Air and Sarnia Area air monitoring website, the winds were from the west and very low at the time of the complaint. All stations were reading in the “good” range. The ministry could not confirm an odour during an inspection. What Actions Were Taken? Ministry staff inspected the area for odours at approximately 10:23 pm. There were no unusual odours found during the inspection. Ministry staff observed the winds were from the west at the time of the inspection and were higher than at the time of the complaint. Ministry staff monitored the area for sulphur dioxide using hand held equipment. There was no detection of sulphur dioxide. Other Agencies/Parties responding: No other agencies.</p>		FB
Mar 19	2:32 pm	2:54 pm	NOVA Corunna	CVECO Code 8	<p>Code 8 was issued for VCW454 at Nova Corunna. For a man down.</p>		
Mar 19	9:12 pm		Arlanxeo	Email from Sarah Macklin, Arlanxeo	<p>I am writing to personally inform you that ARLANXEO will be starting our planned maintenance outage of the Olefins Unit as of Friday March 20, 2020. The outage is planned for approximately 2 weeks, with anticipated start up Monday April 6, 2020. During this time you may see or experience increased flaring and noise associated with shut down activities. With increased flaring, there is the potential for noise and/or smoke. We have added notifications to ECAN, CVECO and the CAER hot line but wanted to reach out to you specifically. If you have any questions or if any concerns arise, please do not hesitate to contact me.</p>		FB
Mar 19	10:24 pm	11:41 pm	CF Industries	Information Notice	<p>CF industries issued information as their nitrogen complex will be shutting down the nitric acid unit. The wind is from the south east at 30 kilometers an hour</p>		
Mar 20	5:49 am	11:41 am Mar 23	Arlanxeo	Information Notice	<p>XJF743 ARLANXEO INFORMATION FOR HIGH FLARING AND NOISE AT BE3 UNIT DUE TO SHUTDOWN</p>		

Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

Mar 22	7:16 am	8:02 am Mar 25	Enbridge	Information Notice	vco420 Enbridge 1010 plank road issuing information for maintenance for 3 consecutive days starting today at 0700. Members of the public may notice petroleum odors, extra traffic around the site and night time work during the duration of this outage. This is planned work and no action is required. Work is scheduled to conclude on Wednesday, March 25 at 0800.		
Mar 24	2:21 pm		Imperial	MECP (SAC) Information Email>>>	<p>MECP Reference Number: 0760-BMZP26 Date/Time Incident Occurred: 2020/03/24 – 13:50 Date/Time Incident Reported to MECP: 2020/03/24 – 13:55 Company name (if known): Imperial Oil Location of Incident: 602 Christina Street South, Sarnia Company description of incident and actual/expected duration: sheen to boomed-off area near outfall in St. Clair River – cause unknown Company description of actual/expected adverse effect: unknown Actions being taken by the facility to respond: investigating/spills response Agencies/Parties responding: n/a</p>		
Mar 24	2:25 pm	8:41 am Mar 25	Imperial	Information Notice	XJF742 – Imperial Oil is issuing an information only. They are responding to a sheen at their outfall.		
Mar 26	10:53 am		Shell Canada	MECP (SAC) Information Email>>>	<p>MECP Reference Number: 3860-BN3JU2. Date/Time Incident Occurred: 03/26/2020 @ 1010h. Date/Time Incident Reported to MECP: 03/26/2020 @ 1020h. Company name: Shell Canada. Location of Incident: 130 St. Clair Parkway, Corunna. Company description of incident and actual/expected duration: Mechanical issues causing process upset. Company description of actual/expected adverse effect: Potential for off site odours but not expected. Operations are scaled down. Actions being taken by the facility to respond: Maintenance contacted to make repairs. Agencies/Parties responding: n/a.</p>		
Mar 27	10:35 am	1:27 pm		Information Notice	INFORMATION ONLY – XJF 739 POSSIBLE ODOURS DUE TO NORMAL MAINTENANCE ACTIVITIES		
Mar 29	11:04 pm	1:52 am Mar 30	CF Industries	Information Notice	Information issued for C F Industries at 161 Bickford Line, C Y A 3 8 9, Nitrogen complex will be starting up the nitric acid unit with the possibility of a slight discharge to the air and loud noise.		
Mar 31	5:51 pm		Suncor	MECP (SAC) Information Email>>>	<p>MECP Reference Number: 5858-BN8TAT Date/Time Incident Occurred: March 31, 2020 at 17:30 Date/Time Incident Reported to MECP: March 31, 2020 at 17:34 Company name (if known): Suncor Sarnia Refinery Location of Incident: 1900 River Road, Sarnia Company description of incident and actual/expected duration: Flare due to equipment failure, followed by black smoke Company description of actual/expected adverse effect: Noise and black smoke Actions being taken by the facility to respond: repairs underway to stop the flare Agencies/Parties responding: NA</p>		
Mar 31	6:46 pm		Suncor	Email from Jennifer	I wanted to make you aware that we had a brief issue in one of our units earlier this evening. In addition to increased flaring and noise, there was also a brief period where community members		

Notification Report -March 2020


Wilson Plain Jr. – Emergency Management Planner

				Meharey, Suncor	may also have noticed black smoke. The issue was corrected within 10 minutes and things are running as per usual. We have communicated this to the Spills Action Centre and CVECO. Please let me know if you have any questions.		
Mar 31	7:04 pm	7:55 pm	Suncor	Information Notice	information only xjf738 suncor. Flaring and noise possible suncor is addressing a minor unit issue.		
Mar 31	8:57 pm	12:56 am Apr 1	CF Industries	Information Notice	INFORMATION ONLY. CYA389 CF INDUSTRIES ISSUING AN INFORMATION ONLY THE CF NITROGREN COMPLEX WILL BE STARTING UP THE NITRIC ACID UNIT MAY EXPERIENCE SMOKEY STACK AND ODOUR WIND FROM THE NORTH AT 13 KILOMETERS AN HOUR.		


Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner

Incident Notifications for the Month of March 2020




Proactive Notifications for the Month of March 2020



Notification Report -March 2020

Wilson Plain Jr. – Emergency Management Planner



CVECO Assistance Codes:

CODE 5- Incident outside of industry potentially requiring CVECO assistance.

CODE 6- Full traffic control requested in designated areas.

CODE 7- Bomb threat.

CODE 8- Notification by a CVECO member of an internal emergency occurrence.
(CVECO will take no action under this code)

Information Notice - Advice by a member of a non-emergency activity that may cause an inquiry.

CODE 9- Request for response by Municipal Fire Department. (Includes **Code 91** and **Code 92**-Specific Fire Equipment)